



## การไฟฟ้าฝ่ายผลิตแห่งประเทศไทย (น้ำพอง)

- The Machine is Cooling Tower
- The old system is Vibration Switches
- The switches sometimes work, sometimes not.
- The inspection team can't get the real vibration data from the gearbox and also can't analyze the root cause of the gearbox's problem
- The customer contacted us to propose a better vibration protection system which also provide a remote spectrum analysis to analyze the root cause
- We propose SENSONICS model DN2601 plus general vibration sensor with splash proof connector, all systems have to response the low frequency of the Fan Blade





# AST



*Most Valued Global Provider of Predictive Maintenance Solution*



*AST*



*Most Valued Global Provider of Predictive Maintenance Solution*




*AST*



*Most Valued Global Provider of Predictive Maintenance Solution*



AST



*Most Valued Global Provider of Predictive Maintenance Solution*

