



Thai Paper-SCG Paper


- The machine is Turbine/Generator.
- The existing system is Bently Nevada, but only at Turbine.
- Some existing cards were failed and the spare parts are very high cost, moreover, they need to monitor the Generator as well.
- AST was awarded to replace the failed existing system as well as installing a new system for the Generator.
- The new system is Rockwell Protection System which is certified API 670, the only standard for Turbine Vibration Protection System.



AST



HMI Display




Most Valued Global Provider of Predictive Maintenance Solution



AST



Completed Sensors Installation




Most Valued Global Provider of Predictive Maintenance Solution



AST



Completed Sensors Installation




Most Valued Global Provider of Predictive Maintenance Solution



AST



Completed Sensors Installation



Most Valued Global Provider of Predictive Maintenance Solution

